

Exelon Generation Company, LLC
LaSalle County Station
2601 North 21st Road
Marseilles, IL 61341-9757

www.exeloncorp.com

January 23, 2004

10 CFR 50.73

United States Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

LaSalle County Station, Unit 1
Facility Operating License Nos. NPF-11
NRC Docket No. 50-373

Subject: Licensee Event Report

In accordance with 10 CFR 50.73 (a)(2)(iv)(A), Exelon Generation Company, (EGC), LLC, is submitting Licensee Event Report Number 03-005-00, Docket No. 050-373.

Should you have any questions concerning this letter, please contact Mr. Glen Kaegi, Regulatory Assurance Manager, at (815) 415-2800.

Respectfully,



Susan Landahl
Plant Manager
LaSalle County Station

Attachment: Licensee Event Report

cc: Regional Administrator - NRC Region III
NRC Senior Resident Inspector - LaSalle County Station

IE22

NRC FORM 366 (7-2001)

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET NUMBER	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
LaSalle County Station, Unit 1	05000373	03	005	00	2 of 4

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

PLANT AND SYSTEM IDENTIFICATION

General Electric - Boiling Water Reactor, 3489 Megawatts Thermal Rated Core Power

A. CONDITION PRIOR TO EVENT

Unit(s): 1

Event Date: 11/27/03

Event Time: 0052

Reactor Mode(s): 1

Power Level(s): 020

Mode(s) Name: Run

B. DESCRIPTION OF EVENT

On 11/27/03, Unit 1 power was being decreased in order to remove the main turbine generator from service to repair a hydrogen leak. At approximately 20 percent power, during the transfer from the 1A Turbine Driven Reactor Feed Pump (TDRFP) to the Motor Driven Reactor Feed Pump (MDRFP), reactor water level started to decrease. At 0052, with the MDRFP indicating maximum flow and reactor water level at 20 inches and continuing to decrease, the reactor was manually scrammed.

Following the scram, the operators secured the 1A TDRFP in accordance with procedure. When the 1A TDRFP discharge isolation valve was closed, feedwater flow from the MDRFP was restored to the vessel.

Investigation determined that the 1A TDRFP discharge check valve 1FW001A had stuck open, which allowed the flow from the MDRFP to circulate back through the 1A TRDFP, preventing feed flow from reaching the reactor vessel. The recirculation path was closed when the discharge isolation valve was closed, and feed flow to the reactor vessel was restored.

This event is reportable under 10 CFR 50.72(b)(2)(iv)(B) and 50.73 (a)(2)(iv)(A) as an event or condition that resulted in the manual actuation of the Reactor Protection System. An ENS notification was made at 0224 CST on 11/27/03.

C. CAUSE OF EVENT

The root cause of the failure was inadequate design. The cross-section of the integral over travel disc stop contact surface, due either to original casting or excessive final grinding during manufacture, was reduced to the point that the disc stop would strike on the angled surface of the seat ring rather than the flat area. This imparted a lateral force to the disc that resulted in binding between the disc hinge ears and the seat ring hinge ears (See Figure 1).

A contributing factor was that the check valve cushioned back stop was missing. The cushioned back stop is designed to give the disc a push closed on vertical installations of the check valve. Although the check valves at LaSalle are installed horizontally, the cushioned back stop could have stopped the disc when swinging open without the disc stop impinging the seat ring. The apparent cause of the missing cushioned back stop was a failure of the tack welds that held it in place.

Other Crane tilting disc check valves that are potentially affected are the discharge check valves for the TDRFPs and MDRFPs on both Units, and the Condensate Booster Motor Driven Reactor Feed Pump supply bypass discharge check valves on both Units.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET NUMBER	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
LaSalle County Station, Unit 1	05000373	03	005	00	3 of 4

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

D. SAFETY ANALYSIS

The safety significance of this event was minimal. All control rods fully inserted and all systems responded as expected to the scram. The Emergency Core Cooling Systems (ECCS) were not challenged. The loss of reactor feed water flow is an analyzed event. The likelihood of a severe accident does not increase as a result of this event.

This event does not constitute a scram with loss of normal heat removal, because feedwater flow from the MDRFP was restored by the control room operators when the 1A TDRFP was secured per post-scram procedures. Neither Reactor Core Isolation Cooling (RCIC) nor ECCS actuated or were required to recover reactor water level.

E. CORRECTIVE ACTIONS

1. TDRFP discharge check valve 1FW001A was inspected, and new hinge pins and a cushioned back stop were installed prior to the restart of Unit 1 on 11/28/03. This action is complete.
2. The integral over travel disc stops for the TDRFP and MDRFP discharge check valves on both Units (1/2FW001A/B and 1/2FW002) and the Condensate Booster Motor Driven Reactor Feed Pump supply bypass discharge check valves on both Units (1/2FW023) will be inspected for proper contact with the seat ring. Where necessary, the assembly will be replaced, or the contact surface area of the disc stop will be increased using weld build-up in accordance with vendor recommendations (AT#188345-29 to 34).
3. The design of the cushioned back stop for the affected valves will be revised to incorporate vendor configuration enhancements and to revise the weld configuration and size (AT# 188345-35, 36).

F. PREVIOUS OCCURRENCES

A search of LaSalle Licensee Event Reports found no previous occurrences of stuck open feed pump discharge check valves.

G. COMPONENT FAILURE DATA

Crane 24 inch Tilting Disc Check Valve, Model 973A.


LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET NUMBER	6. LER NUMBER			3. PAGE
YEAR		SEQUENTIAL NUMBER		REVISION NUMBER	
LaSalle County Station, Unit 1	05000373	03	- 005 -	00	4 of 4

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

Crane Model 973A Tilting Disc Check Valve


Figure 1



Check Valve Assembly



Cushioned Back Stop



Over Travel Disc Stop